

MACI Floor CPC_sample ITC 2 1.txt

01-24-2008	05:54:18.031	N	FI	N01884550554188	XK	Z101Z100000856AM			
01-24-2008	05:54:18.375	N	FI	N01884560554183	XC	F113F110004053AM			
01-24-2008	05:54:20.763	N	FI	N01885090554207	XK	Z111Z110003281AM			
01-24-2008	05:54:21.559	N	FI	N01885360554215	XC	F123F120001227AM			
01-24-2008	08:06:27.780	N	FA	N02084000806278F	XC	F113F112	0019000+T		
01-24-2008	08:06:27.780	N	FH	N02084010806281F	XC	F113F112	0019000+	2	0019000+
01-24-2008	08:06:28.014	N	FA	N02084050806287F	XC	F113F112	0021000+T		
01-24-2008	08:06:28.014	N	FH	N02084060806284F	XC	F113F112	0021000+	2	0019000+
01-24-2008	08:06:28.232	N	FA	N02084140806282F	XC	F123F122	0018950+T		2 0021000+
01-24-2008	08:06:28.232	N	FH	N02084150806286F	XC	F123F122	0018950+	2	0018950+
01-24-2008	08:06:28.451	N	FA	N02084240806285F	XC	F123F122	0020950+T		
01-24-2008	08:06:28.451	N	FH	N02084250806288F	XC	F123F122	0020950+	2	0018950+
01-24-2008	08:06:28.685	N	FA	N02084300806287F	XK	Z101Z102	0009100+T		2 0020950+
01-24-2008	08:06:28.685	N	FH	N02084320806297F	XK	Z101Z102	0009100+	2	0009100+
01-24-2008	08:06:28.919	N	FA	N02084380806289F	XK	Z101Z102	0011100+T		2 0009100+
01-24-2008	08:06:28.919	N	FH	N02084400806293F	XK	Z101Z102	0011100+	2	0011100+
01-24-2008	08:06:29.153	N	FA	N02084450806292F	XK	Z111Z112	0009100+T		
01-24-2008	08:06:29.153	N	FH	N02084460806295F	XK	Z111Z112	0009100+	2	0009100+
01-24-2008	08:06:29.372	N	FA	N02084560806294F	XK	Z111Z112	0011100+T		2 0009100+
01-24-2008	08:06:29.372	N	FH	N02084570806297F	XK	Z111Z112	0011100+	2	0011100+
01-24-2008	08:07:30.110	N	FT	N02106450807301F	XC	F113F112	0021000+TM00020A		
01-24-2008	08:07:30.625	N	FT	N02106620807306F	XC	F123F122	0020950+TM00030A		
01-24-2008	08:07:31.156	N	FT	N02106770807312F	XK	Z101Z102	0011100+TM00005A		
01-24-2008	08:07:31.671	N	FT	N02106960807317F	XK	Z111Z112	0011100+TM00035A		
01-24-2008	08:10:56.784	N	FA	N02143440810568F	XC	F113F112	0020105+T		
01-24-2008	08:10:57.002	N	FA	N02143460810575F	XC	F123F122	0020060+T		
01-24-2008	08:10:57.221	N	FA	N02143480810572F	XK	Z101Z102	0010210+T		
01-24-2008	08:10:57.439	N	FA	N02143500810574F	XK	Z111Z112	0010210+T		
01-24-2008	08:14:34.183	N	FA	N02162230814342F	XC	F113F112	0020815+T		
01-24-2008	08:14:34.401	N	FA	N02162250814344F	XC	F123F122	0020765+T		
01-24-2008	08:14:34.620	N	FA	N02162270814346F	XK	Z101Z102	0010915+T		
01-24-2008	08:14:34.838	N	FA	N02162290814348F	XK	Z111Z112	0010915+T		
01-24-2008	08:18:11.863	N	FA	N02180870818119F	XC	F113F112	0019525+T		
01-24-2008	08:18:12.097	N	FA	N02180890818121F	XC	F123F122	0019480+T		
01-24-2008	08:18:12.300	N	FA	N02180900818123F	XK	Z101Z102	0009630+T		
01-24-2008	08:18:12.518	N	FA	N02180920818125F	XK	Z111Z112	0009630+T		
01-24-2008	08:21:50.042	N	FA	N02205540821509F	XC	F113F112	0020240+T		
01-24-2008	08:21:50.245	N	FA	N02205550821502F	XC	F123F122	0020190+T		
01-24-2008	08:21:50.464	N	FA	N02205600821505F	XK	Z101Z102	0010340+T		
01-24-2008	08:21:50.682	N	FA	N02205650821507F	XK	Z111Z112	0010340+T		
01-24-2008	10:50:42.417	N	FI	N02524001050426	XC	F113F11	0000000AM		
01-24-2008	10:50:42.449	N	FI	N02524011050426	XC	F123F12	0000000AM		
01-24-2008	10:50:42.496	N	FI	N02524021050426	XK	Z101Z10	0000000AM		
01-24-2008	10:50:42.527	N	FI	N02524031050427	XK	Z111Z11	0000000AM		
01-24-2008	12:02:07.085	N	FE	N02530211202074C	XK	Z101Z102	0003255+TM01000AB		
01-24-2008	12:02:10.114	N	FE	N02531071202105C	XK	Z111Z112	0001265+TM01200AB		
01-24-2008	12:02:13.298	N	FE	N02531921202132C	XC	F113F112	0001895+TM06000AB		
01-24-2008	12:02:16.342	N	FE	N02532821202162C	XC	F123F122	0000765+TM03600AB		